



**Sensenich has compiled a list of serial numbers of some of our older propeller models starting with the letter prefix "B".**

Some serial numbers below are not in sequence. The serial numbers are issued during blank manufacture, with some blanks remaining on the shelf for up to several years.

If your Sensenich Wood Propeller has a non-letter prefix or an "A" prefix serial number, your propeller was manufactured between 1932 and 1942

If you wish to know what aircraft your propeller could have been used on, go to our Installation Guide. Look for your propeller model. Sensenich does not keep a history of what aircraft specific propellers were installed on.

- S/N's B4128 TO B9199 were manufactured between 10/43 & 12/43
- S/N's B4128 TO B9199 were manufactured between 10/43 & 12/43
- S/N's B9200 TO D8399 were manufactured between 1/44 & 6/44
- S/N's D8400 TO E6799 were manufactured between 6/44 & 10/44
- S/N's E6800 TO F0399 were manufactured between 10/44 & 3/45
- S/N's F0400 TO F9400 were manufactured between 3/45 & 9/45
- S/N's F9401 TO G8200 were manufactured between 9/45 & 12/45
- S/N's G8201 TO H9099 were manufactured between 12/45 & 4/46
- S/N's H9100 TO K5099 were manufactured between 4/46 & 8/46
- S/N's K5100 TO L4099 were manufactured between 8/46 & 10/46
- S/N's L4100 TO L9999 were manufactured between 10/46 & 11/49
- S/N's M0001 TO M0099 were manufactured between 10/46 & 11/46
- S/N's M0100 TO M1599 were manufactured between 11/46 & 11/46
- S/N's M1600 TO M3099 were manufactured between 1/47 & 11/46

87781

- S/N's M3100 TO M4599 were manufactured between 11/46 & 12/46
- S/N's M4600 TO M6999 were manufactured between 1/47 & 12/46
- S/N's M6100 TO M7599 were manufactured between 1/47 & 11/48
- S/N's N2100 TO N3599 were manufactured between 1/47 & 1/47
- S/N's N3600 TO N5099 were manufactured between 2/47 & 3/47
- S/N's N5100 TO N6599 were manufactured between 3/47 & 3/47
- S/N's N6600 TO N8099 were manufactured between 3/47 & 4/47
- S/N's N8100 TO N9599 were manufactured between 4/47 & 8/47
- S/N's N9600 TO P1100 were manufactured between 5/48 & 1/48
- S/N's P1101 TO P2599 were manufactured between 5/47 & 6/47
- S/N's P2600 TO P4099 were manufactured between 6/47 & 4/48
- S/N's P4100 TO P5599 were manufactured between 1/48 & 5/47
- S/N's P5600 TO P7099 were manufactured between 7/47 & 9/47
- S/N's P7100 TO P8599 were manufactured between 9/47 & 12/47
- S/N's P8600 TO R0100 were manufactured between 7/52 & 5/48
- S/N's R0101 TO R1600 were manufactured between 8/48 & 5/48
- S/N's R1602 TO R3100 were manufactured between 7/48 & 5/48
- S/N's R3101 TO R4599 were manufactured between 4/53 & 8/48
- S/N's R4601 TO R6100 were manufactured between 8/48 & 1/49
- S/N's R6101 TO R7599 were manufactured between 1/49 & 7/51
- S/N's R7600 TO R9099 were manufactured between 12/48 & 8/49
- S/N's R9105 TO R9999 were manufactured between 8/49 & 7/52
- S/N S9020 was manufactured 8/53
- S/N T6024 was manufactured 6/54

- S/N's W0001 TO W1999 were manufactured between 3/58 & 8/59
- S/N's W2002 TO W3499 were manufactured between 12/59 & 9/60
- S/N's W3502 TO W4998 were manufactured between 2/61 & 11/62
- S/N's W5000 TO W6999 were manufactured between 9/62 & 11/64
- S/N's W7000 TO W9000 were manufactured between 7/65 & 11/66
- S/N's W9002 TO W9995 were manufactured between 2/67 & 5/68
- S/N's Y0001 TO Y1999 were manufactured between 4/68 & 10/69
- S/N's Y2001 TO Y4099 were manufactured between 2/70 & 9/71
- S/N's Y4100 TO Y6099 were manufactured between 9/71 & 5/73
- S/N's Y6100 TO Y8199 were manufactured between 2/73 & 6/74
- S/N's Y8200 TO Y10000 were manufactured between 8/74 & 8/75
- S/N's Z0001 TO Z1996 were manufactured between 5/75 & 3/77
- S/N's Z1997 TO Z3997 were manufactured between 3/77 & 5/78
- S/N's Z3998 TO Z5999 were manufactured between 5/78 & 7/79
- S/N's Z6000 TO Z7997 were manufactured between 7/79 & 5/80
- S/N's Z7998 TO Z9998 were manufactured between 5/80 & 10/81
- S/N's AA0001 TO AA1989 were manufactured between 10/81 & 11/82
- S/N's AA1990 TO AA3996 were manufactured between 11/82 & 2/84
- S/N's AA3997 TO AA5994 were manufactured between 2/84 & 11/84
- S/N's AA5995 TO AA6643 were manufactured between 11/84 & 6/85
- S/N's AA6644 TO AA9025 were manufactured between 6/85 & 11/86
- S/N's AB0033 TO AB2983 were manufactured between 3/87 & 11/88
- S/N's AB2984 TO AB6788 were manufactured between 11/88 & 7/90
- S/N's AB6789 TO AB8990 were manufactured between 7/90 & 8/91

- S/N's AA9934 TO AA10478 were manufactured between 11/91 & 3/92
- S/N's AC0078 TO AC3137 were manufactured between 3/92 & 4/93

[Airboat Props](#) [Aircraft Props](#) [Display Props](#)  
[Home](#) [Repairs](#) [UAV Props](#) [Support](#)